



Technical Bulletin

(1005326 Rev. A)

June 26, 2006

Models Affected:

1003836 (RL-18)

Model Serial Numbers:

142256-142260, 142509-142513, 142576, 142577, 142598-142612, 142729-142739, 143074-143086, 143190-143198, 143388-143390, 143412-143420, 143787-143790, 144043, 144044, 144529, 144530, 144981-144989

Details:

After lifting the monitor it is possible for the power & video cables to fold behind the monitor hinge. If the monitor is lowered with the cables folded behind the monitor hinge, the cables can be damaged by the monitor.

Solution:

Visually inspect the position of the monitor cables when positioning the monitor back into the case.

Rework Instructions:

Directions

1. Before lowering the monitor ensure the cables stay as close as possible to the front and right walls of the case. Refer to figure 1 below for proper cable position.




Figure 1